



Technical Service Information Bulletin

August 28, 2006

Title:

VANITY MIRROR LIGHT FLICKER

Models:

'07 ES 350

ELECTRICAL
EL009-06

Introduction Customers may experience the vanity mirror light flicker during movement of the visor assembly. The visor assembly has been changed to improve the condition.

Applicable Vehicles

- **2007** model year **ES 350** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

**Production
Change
Information**

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
ES 350	JTHBJ46G#72012509

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
74310-33A50-A0	Same	Visor Assembly, RH	1
74310-33A50-B0			1
74320-33A40-A0		Visor Assembly, LH	1
74320-33A40-B0			1

**Repair
Procedure**

Replace the visor assembly.

Refer to the Technical Information System (TIS), 2007 model year ES 350 Repair Manual: *Interior: Roof Headlining: Removal*.

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
752101	R & R Left and/or Right Visor Assembly	0.2	74310-33A50-## 74320-33A40-##	82	73

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Lexus Supports ASE Certification