



Technical Service Information Bulletin

March 2, 2006

Title:

INSTALLATION OF BODY PLUGS DURING PDS

Models:

'07 ES 350

PD010-06

PRE-DELIVERY SERVICE

Introduction The ES 350 is equipped with front and rear torque box holes to tie down the vehicle during transportation. Rubber body plugs need to be installed during Pre-Delivery Service (PDS).


Applicable Vehicles

- 2007 model year **ES 350** vehicles.

Installation Procedure Four (4) rubber body plugs are included in the glove compartment at the assembly plant. Install them into the two (2) front and two (2) rear torque box holes located under the vehicle on both sides.

NOTE:

If the rubber body plugs are NOT securely installed, road (tire) noise may transfer to the vehicle interior through the torque box holes.



Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	—	—	—	—



Lexus Supports ASE Certification